



Company:
Lindum BMS

Location:
Beaumont Fee, Lincoln

RILMAC

Scaffolding

BEAUMONT FEE CASE STUDY



The unsafe wall at Beaumont Lee



The Scaffolding Solution

Rilmac Scaffolding

Greetwell Road, Lincoln,
Lincolnshire LN3 4NH

T: +44 (0)1522 545680
E: enquiries@rilmac.co.uk
W: rilmac.co.uk/scaffolding

Unit 3, The Scorpion Centre,
19-21 Hartburn Close,
Crow Lane Industrial Estate,
Northamptonshire NN3 9UE

T: +44 (0)1604 659788
E: enquiries@rilmac.co.uk
W: rilmac.co.uk/scaffolding

[in /company/rilmac-group](https://www.linkedin.com/company/rilmac-group)

[@RilmacGroup](https://twitter.com/RilmacGroup)

[f /Rilmac-Group](https://www.facebook.com/Rilmac-Group)

Testing on a supporting wall at Beaumont Fee, Lincoln had shown that it had become quite unsafe. This meant that immediate and rapid works were required to solve the issue. Rilmac Scaffolding were employed by Lindum BMS to provide support scaffolding keeping the site safe while the wall was demolished. Nearly 12 tons of scaffolding was required, covering 11m x 3.6m x 4m, and was erected across 2 evenings, with teams working until it got dark. Rilmac were able to prepare drawings and build the scaffolding well within deadline, allowing for the wall to be made secure quickly and safely.