

FARMLAND ASBESTOS REMOVAL



- Project:
 Farmland Asbestos
 Removal
- Client:
- Location: Worksop
- **№** Value: £8,500
- Time Scale:
 October 2017

CASE STUDY

Fire damaged barn on farm.

Removal and disposal of asbestos cement debris, contaminated straw and remaining asbestos cement sheets using our supplied 8 tonne excavator and MEWP.

